

Andrej Cimperšek - diploma - Bug #177

Serial port

07/14/2010 05:44 PM - Andrej Cimperšek

Status:	Closed	Start date:	07/14/2010
Priority:	Normal	Due date:	
Assignee:	Andrej Cimperšek	% Done:	70%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Description			
Testiranje delovanje naprav LIDARja z uporabo JavaComm + implementacija APIja.			

History

#1 - 07/15/2010 11:33 AM - Andrej Cimperšek

- Status changed from New to Assigned

- % Done changed from 10 to 70

Porti so zaznani kot /dev/ttyUSBX.

Preverjeno deluje Laser, motorja ne morem sprobati ker en ne deluje, za Senzor potrebno poslati gain, da začne zajemati podatke - bi tudi moral delovati.

Potrebno aktivirati modul usbserial: sudo modprobe usbserial.

V /usr/lib/jvm/java-6-openjdk/jre/lib/javax.comm.properties potrebno dodati:

```
serpath2 = /dev/ttyUSB0
serpath3 = /dev/ttyUSB1
serpath4 = /dev/ttyUSB2
```

#2 - 02/14/2011 11:53 PM - Andrej Cimperšek

- Status changed from Assigned to Closed